

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.







BUICK CLUB

1569 WABASH AVENUE, SPRINGFIELD, ILLINOIS 62704

3825 South Second Street, Springfield, Illinois 62703

Dear Members.

It's been awhile since I published a Newsletter and I know you are all quite anxious to hear the members responce to the depressing letter I sent January 20th. I was very impressed with the mail as it has poured in the last three weeks. I had forgotten we had that many members...Of the 365 letters that were mailed I have received 267 replys. Of that 264 voted to continue the Club and make what ever changes that was necessary. Some voted to run the Newsletter bi-monthly year around and several voted to raise the dues. After reviewing all of them I decided to make only the changes that I listed in the letter and not to raise the annual dues. I also made a third change that I did not mention. That is that we will not pro-rate membership dues like I did last year for members that join during the year. It will be the same price when ever they join although all memberships will expire January 30 each year. Checking with other clubs, this seems to be the way they are run also. It's a must to keep book work at a minimum even though you may make some people un-happy. At this time 102 members have not replied to my letter. I don't know if this means they dis-approve of my actions or they are too busy to sit down and write a letter. In hopes they will re-join us for 83 I will hold off until next issue to print our 83 Rositer. Most of the members have paid their 83 Dues and some were waiting for this report to send theirs in. Please for those of you who have not sent your dues in, please do so now.

This is the final issue for members of 1982 so if your dues are not in you will not receive the next issue which will be Volume #2 Issue #1. I will extend my offer to refund anyones money for the last two issues of 1982 if they feel they were shorted. I feel this is a personal obligation as you all joined and paid expecting 12 issues and received only 10. I will extend this offer until the end of March as I don't want anyone

out there saying that I cheated you. Please let me know your feelings.

Three of the members wanted to know where all the money went from 82. I sent them an explanation on all of our income and expence for 1982. They stated a lot of the members felt this way, so if any of you want this information, please contact me as it is available to any paying member. I have mixed feelings about publishing our finances because I don't like the idea of the general public having access to it. Since our finances have improved dramatically for 1983 I will correct my objections and be sending a financial statement to each member annualy.

With the reduced Publications and membership at 378 (Hopefully) we will have an excess cash amount in our account. Probably at mid-year I will report on our finances and we can decide how these monies are to be used. If we take in the full \$7,560 with an expence average of \$475.00 per issue (9), we should have around \$3,200.00 in reserve. We could use this however the members want. I WANT NONE OF IT... Possibly we could use it for membership card, Jacket Patches, Decals, Car Show or any number of things for the members. I'll keep you posted on memberships for 83 and any other plant we have

I'll keep you posted on memberships for 83 and any other plans we have.

I am starting on VOL #2 Issue #1 Now so start writing those letters......

THANKS FOR YOUR SUPPORT..IT MEANS A LOT TO ME.....

Dave Lewis /







BUICK CLUB

3825 SOUTH SECOND STREET...SPRINGFIELD, ILLINOIS 62703
BUICK CLUB RULES & REGULATIONS 1983 EFFECTIVE 1-1-83
POLICYS

A INDIVIDUAL MEMBERSHIPS

You must be the proud owner of any model 37/38 Buick or in the pursuit of..

You must understand that the sole purpose of this Club is to preserve and to maintain these fine cars.

You must participate in some form during the course of your membership.

You must treat your fellow members as "Hobbiest" rather than use the Club For Profi

All members are entitled to "Free" Advertising to fellow members with exception of "Commercial Vendors" who must pay Commercial Rates.

The Editor reserves the right to refuse Advertising to any Commercial Vendor that engages in Un-Ethical Practices or Advertises Goods that are not up to Claims.

B NON-MEMBER ADVERTISING

Non-Members will be allowed Advertising Free for the purposes of Selling Parts or Cars that are 37/38 Buicks.

C NEW POLICYS 1983

The Newsletter will be published Nine times per year instead of twelve. It will be Bi-Monthly thru the six months of summer

Volume #1 Issue #10 will be the final issue for 1982.

The above changes were voted on by the majority of the members to be effective February 1,1983.

D DUES & POSTAGE RATES

Annual Dues, United States, Bulk Rate Postage....\$20.00 Annual Dues, United States, First Class Postage...\$26.00 Annual Dues, Canada, First Class Only......\$26.00 Annual Dues Foreign Countries, First Class Air...\$45.00

Fiscal Year of Club. February 1 thru End of January All Memberships expire on January 30 each year. Membership Fees will not be prorated at any time....

E COMMERCIAL ADVERTISING RATES

Full Page...\$35.00 Half Page...\$20.00 Quarter Page....\$10.00 Business Card...\$7.50







COVER CAR

1938 BUICK SPECIAL CONVERTABLE. TERRY TATUM #37

This beautiful 1938 Model 46C is Maroon in color and is one of the finest 38's in the Country. Terry bought the Car in St. Louis, Mo. in January of 1981. He paid \$5,000.00 and a 1947 Cadillac Convertable in trade. Since that time Terry has rebuilt the transmission, installed a new clutch and new lifters in the engine. Other improvements have been a new carb, fuel pump and a set of Bill Hirsch's Hub Caps. At this point the car is 99% complete and driven every week-end. It really turns the heads when he drives this beauty down the street.









BUICK CLUB

MEMBERSHIP APPLICATION 1983

NAME	ADDRESS	-
СІТУ	STATE	ZIP
DATEAMOUN	T ENCLOSED \$	
EXACT MODEL BUICK	CONDITION	SCALE FROM 1 to 10(1-NEW)
HOME PHONE	WORK PHON	NEINCLUDE A/C
PLEASE READ ALL CLUB RU	LES & REGULATIONS BEFOR	RE APPLYING FOR MEMBERSHIP
MAIL APPLICATIONS TO	CLUB OFFICE: 3825 SOUT	TH SECOND STREET, SPRINGFIELD, ILL 62703

1937 and 1938 Buick Series 90 RUNNING BOARD COVERS..ATTENTION OWNERS..... By; STEVE SCHWARTZ #170

A project to remold series 90 Running Board Covers ONTO YOUR EXISTING METAL is currently being developed. If sufficient interest is expressed, a mold will be tooled in early 1983 with delivery expected by fall 1983. Cost is expected to be in the \$425.00 to \$450.00 range plus shipping for the pair. For additional Details send a S.A.S.E. to..

STEVE SCHWARTZ #170...8621 BEEKMAN DRIVE...MIRAMAR, FLORIDA 33025....OR TO;

DENNIS PETERS.....3950 Clippert... Dearborn Heights, Michigan 48125



Dave Lewis, Editor







Dear Dave,

I need some information on the front compartment of my 37-91F Limo, as to use Leather or Mohair on the Seat, Door Panels and Kick Panels. I was told the Sloan Museum had a lot of information on our Buicks. I have been to Flint, Michigan and they can't help, or won't. Maybe you can help, or one of the members can. Either way I would be very grateful. This bit of information maybe helpful to others also.

A question and Answer Corner might be interesting in the 37/38 Newsletter. If you

have any information on the Sloan Museum I would like to know.

P.S. Does anyone know of another 37-91F...I think I have the only one left.

Jack Corliss

Sincerly,

Jack Corliss #279

Dear Jack.

As to your question on the interior of your Limo. I am sorry I do not know, but I would guess it would be done in Leather. From what I've read on the Limo's they were all done in leather in the Front only. On page 19 of issue #7 is the Trim combinations that were offered for your car. This information was sent to me from Buick. As to information on the Sloan Museum. Our Technical Director, Paul Brennan, has been in close contact with them and there is a copy of their recent letter to Paul in this issue. It gives all the information they have available to copy for you.

If any of the members can help Jack with some solid information, please write and

let him know.

Dave A BUT

Dear Dave.

First of all I want to tell you it is a very good job and one that is really appreciated. Your organizing the "37/38" Buick Club. I am sorry that I have not been able to help.

I was looking through the issue #6 again and reading the idea of having different members helping out by taking over some of the different parts of Club work. I think it would be a very good idea as it has been working in some of the other clubs. That way each person would only have one part to be responsible for. If I can be of any help, please let me know.

I was looking over the Designs that Dug drew for the Club Emblem and they were real nice. I like emblem "B" as it would make a very distinct emblem and decal or patch. It would be different and not easily confused with the National Buick Emblem. I think

we should be recognized on our own.

Nat Burgess #119





ROUD 1938 OW

GRANDPA'S CAR. . By PAUL BRENNAN #71

Back in the fall of 1937 my grandfather bought his Buick; a new 1938 Special Model 41. This was his first G.M. car, as he had always owned Maxwells sice buying his first new one back in the teens. With 1925 being the final year for Maxwell, the local dealer here in town sold Nash cars for a few years. The Nash wasn't all that popular here because they had a reputation for hard starting in the cold weather. It was about this time that the Cleaverland Garage took on the Buick line and since Grandpa had always purchased his cars there, his new one that fall would once again come from the Clererland Garage.

The salesman had talked to Grandpa and knew he was looking for a new automobile. When the first '38 came in at the dealership, as was the custom, it was fitted with just about every Buick dealer accessory. The salesman drove the car to my grandparents' house for a demonstration, and Grandpa bought it. I can still remember him saying, when I was a kid, that the price was \$900.00 and the old folks spoke of the Buick as "The Pride of North Marquette", when it was new. I am sure it was an impressive car at the time. Even now, forty five years later, it still is..

With this new "Luxury Car" traveling was no longer the chore it once was with the old four cylinder open cars, so the family agreed to do some traveling. A trip "out west" was planned. One interesting part of this trip was, while in Seattle, a Buick Dealer approached them, told them that he couldn't get any new Buicks, and wanted to buy the car. He offered-Grandpa \$1,000.00 cash, the family could stay at his place a few days while he showed them around Seattle, and he would pay their train fare back home to Marquette! The answer was "NO"! Grandpa liked his cat too much to part with it.

I lived with my Grandparents while growing up. My first memories of the old Buick were on saturday mornings during the summers. We would load up the trunk of the Buick with trash, stop and deposit it at the city dump, and then drive the county road to the Carp River for some fishing. This was a treat my older brother and I looked forward to each week-end during the summer. In the winter the Buick was kept in the garage a lot. in fact, the first few years when the car was still "new", it was kept in the garage on small sawhorses all

winter. It was only used for the summer months.

We are all familiar with the rather limited visability in our Buicks, and for a small child sitting down in the deep expanses of the rear seat, there was nothing to see except the interior, which was a world of upholstery. My younger brother and I would sit on the armrests in the back seat and hold on to the assist straps. This worked out just fine, and during a trip to Pittsburg when we were small, we rode in this manner most of the way. I can still remember playing some of the "How Many Can You Find" games while looking out the windows.

In later years came driving lessons for my brothers and I in the old Buick. Less than a block away from our house was a very large baseball diamond where the circus' sometimes set up when they came to town. This was the place that Grandpa chose to teach us how to drive. My older brother, younger brother and I, all did our first driving there with

Grandpa in the old Buick.

Grandpa quit driving in the late 1950's...his first Buick was also his last car. The Grand Old automobile sat in his garage, where he parked it, for over two decades. In May of 1981 I took it out and brought it home to my own garage, where I've been cleaning it up, making a few adjustments, and correcting some minor ills. The car is not restored, just a very well taken care of old automobile that I,m proud to own...and just as important, all of those wonderful memories that go with that Old Buick are as much a part of owning it as is the car itself.

In closing, I'll say that our Club has made "Grandpas Car" even more enjoyable for me.

I'm glad to be a member ... and to Dave, my Thanks.

(Photos Next Page)

Paul Brennan #71 Technical Director



PROUD 1938 OWNER

1938 Series 41. Paul Brennan #71... Technical Director 37/38 Buick Club






Where There's Roadmaster There's *Life*

THERE was a day, and not so long ago, when you had to choose between the comfort of size and the thrill of brilliant behavior if your tastes ran to a car in the general price range of the Buick ROADMASTER.

But here's a car only three inches short of eighteen feet, with interior room to spare and the solid, roadsteadiness of ample weight—yet it can step you up from ten to sixty in eighteen seconds flat, produce all the m.p.h. you'll ever need, and, in Proving Ground tests, deliver 16.5 miles per gallon at thirty!

Such statistics are impressive. But even they fail to picture the life and spirit of this truly great traveler. It is that spirit that puts ROADMASTER so much in evidence today wherever life and action have the call; when you've tried it we think you, too, will wonder if ROADMASTER has any equal within a thousand dollars of its price!

WHEN BETTER AUTOMOBILES ARE BUILT BUICK WILL BUILD THEM





PARTS FOR SALE

37 Banjo Steering Wheel, no plastic \$50 37 80/90 Series Nose Skelton \$75 37 60 Series Windshield Frame \$20 37/38 Sidemount Lock Nuts \$7 ea. 37/38 Sidemount Nameplates \$42.50 ea. Reproductions Jack Corliss#279 8735 Lyndora Downey, CA 90242

Windshield Center Divider Strip Outside. Reproduction in Stainless Steel. I think all models are the same length, but you better measure your old one and include that with your order. \$15 includes postage. Allow 4-6 weeks for delivery.

E.T. Doucette #220 PSC 1 Box 4738 APO S.F. 96286

37 Trunk Lid (Model 41) Sandblasted \$50

37 Doors (Model 41 \$75 set

37 Trunk Lid Hold Open Hindge \$5

37/38 Front Wing Vents (Good Shape) \$35 set

38 Running Board Moldings, Special Ser. \$25 38 Running Board Brackets 40/60 Ser. \$25 set

38 Front Bumper 40/60 Ser \$40

38 Rear Bumper 40/60 Ser \$40

38 Brake & Clutch Pedal Ass., Cleaned & Painted & New Bushing \$25

38 Licience Plate Light, Cover & Lens \$5

38 Rear Bumper Brkts 40/60 Ser \$20 set

38 Dome Lens \$5

38 Trunk Hold Open Hindge \$10

38 Ash Trays \$10 set

38-60 Nose Skeleton \$45

38 Side Panels for Limited and Century \$55 ea. Nose Trim with Emblem \$15

38 Hood with Center Chrome 60 Ser \$100

38 Owners Manual, Original \$30

David Bylsma #117 1724 Green Meadow Ct. Severn, MD 21144

1937 and 1938 Spark Plug Cover for large series engines, Very Good used \$40 1937 N.O.S. Oil Pressure Gauge \$10 1937 N.O.S. Amps Gauge \$10 1938 N.O.S. Oil Pressure Gauge \$10 N.O.S. Steel Shim Headgaskets for all series \$10 ea.

All Plus Shipping

Bob Pipkin #76 2516 62ed S.E. Salem, OR 97301 503-363-4712 Evenings only Pair of Sidemount Covers, less emblems and small stainless around emblems. \$200 for pair plus shipping.

Lyle Pierson 2306 Lockhaven Colorado Springs, CO 80909

FOR SALE; 38 Special

Front Fenders, non welled \$75 ea. VG Nose Cone \$15 Nose Trim \$8 Grill Should Re-chrome \$40 Hood \$25 Hood Side Panels \$15ea. Headlamps, missing one reflector \$25 pr. Headlight Switch \$5 Park Light Base & Chrome \$8 Park Light Lens N.O.S.\$25 pr. Radiator \$50 Air Cleaner, Dry Type Small \$5 Pistons-Set Part # 1394596 .020 over after engine # 43530562 N.O.S., but pins have some slight rust from moisture \$40 set Horn \$15 pr. Trim Rings 16", some dents \$5 ea. Rear Fenders \$20 ea. Tail Light Complete \$10 R/S Tail Light Left, Base W/ Socket only \$4 Rear Licence Plate Light Ass. Some pits \$5 Radio Grill & Map Light (Cover Poor) \$6 Battery Base & Top, No Bolts \$15 Steering Col with Lock, no keys \$8 Instrument Cluster, Bad Water Gauge \$25 Glove Box Door & Clock Cond ? \$8

Louis Wildt #245 4036 McMann Rd. Cin, OH 45245--513-752-1099

PAGE 9



PARTS FOR SALE

PARTING OUT 1937 ROADMASTER; No Engine, Plain Fenders. Bad Wood in doors has been replaced. Send List of Needs....

Bob Ward #114 RR #1 Sutton West, Ontario, Canada LOE 1R0

BUICK PLASTIC REPRODUCTIONS ..

The list below was sent to me a few months ago and I thought it was worth repeating as the members keep asking where they can find them. So Please check on current prices before you place any orders as they may be higher.

1937 BUICK PLASTIC REPRODUCTIONS Headlight Knob \$4 Throttle Knob \$4 Cigar Lighter Knob \$4 Windshield Wiper Knob \$4 Front Ash Tray Knob \$4 Heater Door Knobs \$8 pr. Door Lock Buttons \$8 pr. Radio Knobs \$8 pr. Horn Bezel \$16 Gear Shift Knob \$12 Glove Box Knob \$6 Rear Ash Tray Knobs \$10 pr. Door & Window Escutcheons \$3 ea. Window Crank Knobs \$4 Also have limited supply of original Door & Window Handles with excellent chrome & Plastic knobs. Window Cranks \$8 ea Door Handles \$4

1938 BUICK PLASTIC REPRODUCTIONS
Headlight Knob \$4
Throttle Knob \$4
Windshield Wiper Knob \$4
Window Crank Knobs \$4
Front Ash Tray Pulls \$10 pr.
Heater Door Knobs \$8 pr.
Door Lock Buttons \$8 pr.
Radio Knobs \$8 pr.
Window Trim \$8 ea.
Gear Shift Knobs \$12

NEXT COL ..

From Last Col

Glove Box Ring \$8 Maplight Covers \$30 ea. Door & Window Escutcheons \$3 ea.

Also have limited supply of original door 8 window handles with excellent chrome 8 plastic.
Window Cranks \$8 ea.
Door Handles \$4 ea.

MEMBERS... This is an old list so check before ordering for prices & Availabilit

BUICK PLASTIC REPRODUCTIONS 10534 Nassau Ave. Sunland, CA 91040 213-353-4303 (Frank)

PARTS FOR SALE;

Hubcaps restored originals \$150 set /4
37 Deluxe Heater with defroster motor \$5
No Defroster ducts, heater needs restore
38 Battery Box, lower \$15 VG
37 Marvel Carb & Choke \$100 Late Style
37 Marvel Carb & Choke \$50 Early Style
38 ser 41 Doors For Parts only
37-61 Garnish Moldings \$7 ea.
37 Radio for parts \$50
38 Seat Tracks \$10
37-60 Rear End, No Shipping \$100
38-40 Engine \$100 No Acc. & stuck
37-60 Engine for parts \$75

Dave Lewis#237 3825 So Second St Springfield, Ill 62703 217-529-5083

Literature for sale

Engineering Information for Factory [Not Bound] \$15
1938 Buick Radio Manual for Centerline & Centerline Dual Radio \$8
1938 Buick Parts Substitution List, Great for Swap Meets \$2
ALL THREE FOR \$22.50 PP
PAUL CUSANO #52 266 Passaic Ave
Hasbrouck Heights, N.J. 07604



PARTS WANTED

INFORMATION WANTED: Could someone out there help me identify the motor in my '37 Buick. The Seriel Number is...68-27034-4. We would appreciate any help offered.

DON YOKEL #75 100 Farmingdale Dr. Wexford, PA 15090 412-935-1436 (H) 412-761-9902 (W)

WANTED for 1938-46C MAP LIGHT COVER, Mint or REPO. GAS TANK RUMBLE SEAT SPRINGS

LOU WILDT #245 4036 McMann Rd. Cincinnati, OH 45245 513-752-1099 Before 2 P.M. E.S.T.

WANTED.. 1938 Century Motor Mounts.. In any Shape.. I need the metal so I can get them re-molded. If you have any Rear Mounts drop me a line. Please Condition and Price.

DAVID BYLSMA #117 1724 Green Meadow Ct. Severn, MD 21144

WANTED FOR '37 ROADMASTER....
Lower A-Arm Bushings, Inner & Outer.
including Pins. Total of &.
Rear Motor Mounts, Prefer N.O.S.
or Reproductions.
2-16" Wheels.

ALLAN COHEN #46 325 Stuart Ave. Downingtown, PA 19335

WANTED 1937 90 SERIES.....

Left Sidemount Tread Cover.

Inside Windshield Garnish Molding.

Nice Pair of "Limited" Name Plates, Hood-

JACK CORLISS #279 8735 Lyndora Downey, CA 90242 213-861-5783 WANTED FOR 1938 SERIES 41..

Set of 8 Rods converted to inserte bearings or later Rods that have inserts that will fit my engine.

Drivers Door, must be excellent Locks for Sidemounts (2)

Center Grill Molding

CARPET GALLERY (JAY) #26 21 E. Clinton Street Newton, N.J. 07860 201-383-5435

WANTED 1937 SERIES 41 N.O.S. or N.O.R.S. Rocker Arms or Full Rocker Arm Assembly.

Mark Davis #356 108 Haven Ave. Staten Island, N.Y. 10306

WANTED FOR 1938 BUICK 41X-EXPORT MODEL....

Choke Control Cable For AA-1
Windshield Washer Assembly
Windshiel Wiper Nozzels or Wiper Trans.,
with Washer Nozzels.
Wiring Diagram for Right Hand Drive.
Rear Lic. Plate Light Lens.
Rear Window Shade Assembly

Ed Doucette PSC #1, Box 4738 APO, San Francisco, CA 96286

WANTED: 1938 40-Series; Starter Switch for Stromberg AA-1 Acrylic Enamel Color Formula for "Gainsborough Blue"

Richard Parks #169
5243 Dallas Drive
Kamloops, B.C.
Canada V2C 4W4

PAGE 11



PARTS WANTED

WANTED: 1938 CONVERTABLE COUPE

Pair of Sidemount Locks
Pair of Sidemount "Buick" Emblems
Pair of Sidemount Moulding Strips
Bumper Step Plate for access to Rumble
Seat.
One Locking Door Handle
One Century Convertable Frame. MUST BE
made of the heavier gauge Steel used
on Convertables only.

WANTED: 1937 CONVERTABLE SEDAN

4-Chrome Plated Door Locking Buttons 1-Locking Door Handle 1-Pair of Sidemount Locks 1-Wheel Jack

JACK SHEPHERD #138
P.O. Box 535
Prince Rupert B.C.
Canada V&J 3R5
604-627-7395 Evenings
604-627-1318 Days, Exc. Sunday & Mon.

WANTED; 1938 46C Convertable
Complete Rumble Seat Lock & Stricker
Rear Gravel Shield at Bumper
Clips that hold Vacume line to Gas Line
Choke Cable Cover (Rubber)
Sending Unit for Fuel Tank
Water Temp Gauge with Line
Trans Crossmember & Mount
Buick Heater Complete
Instrument Light Switch

WANTED FOR 1937 McLaughlin BUICK 4-Hubcaps..Not as flat as the American Version. More rounded like Pontiac & Chev. Name Script is the Same as the American Buick, only the shape of the hubcap is different, more rounded.

Joe Arbini #359 874 E. Main Street Stamford, CT 06902 WANTED: 1937 Buick

Heater & Defroster Switches 2-Acorn Nuts for Spark Plug Cover Someone to reproduce Firewall I.D. Plate

BEN LEWIS #94 5283 Olive Dr. Concord, CA 94521 415-689-7454

WANTED: 1938 MODEL 81 PARTS

ALL MUST BE IN EXCELLENT CONDITION

All Belt Moldings
Sill Plates
Hood Sides Stainless Moldings
NEW Vacume Advance Delco #681H
Glove Box Lock
Hood Ornament
Trunk Emblem
Parking Light Bezels
Heater & Defroster System
Deck Lid Handle & Bezel

Joseph Giordano #333 131 N. Stewart Rd. Liberty, MO 64068 816-781-5570

WANTED: 1937 Series 41

MINT, Owners Manual, Original Only
MINT, Rear Gravel Shield
Tool Kit for Trunk, Originals only
One Sidemount Buick Emblem, MINT ONLY
Oil Bath Air Cleaner Complete
Genuine 37 Spotlight
MINT Color Sales Catalog (Black Cover)
ORIGINAL JACK AS PICTURED IN OWNERS MANUAL
N.O.S. HOOD CENTER STAINLESS STRIP
N.O.S. inside Door Handles & Winders
Rear Fold Down Bumper Guard

PARTS WANTED...1938 SERIES 90

NEED GOOD STARTER AND SOLINOID PART # 727W.....1936-1937 &1938 SERIES 60-80-90 WILL FIT

Glenn SEYMOUR # 345...8 CEDAR ST. POTSDAM, N.Y. 13676



CARS FOR SALE

FOR SALE: 1937 Buick Special Touring Sedan (Model 41). It is a New Mexico Car that is currently being used as a second car in Arizona. Asking Price is \$3,300.00

BUTCH EICHELBERGER #329 1369 S. DESERT CREST DRIVE TUCSON, ARIZONA 85713 602-624-0635



FOR SALE: 1937 Buick, Business Coupe, Black/Tan. Acquired to settle Lawsuit and eager to sell so priced accordingly. New Interior, Tires, Brakes, Hubcaps and Beauty Rings. Also has New Steering Wheel, Total Wireing, Ignition System, Runningboard Rubber and Exhaust System. PRICE \$8,400.00. Write or Call for details and listing of spare parts.

MIKE MILBANK #321 1544 DOMINION AVE. SUNNYVALE, CAL. 94087 408-738-3440 HOME 415-543-8030 WORK

ATTENTION MEMBERS.....


MR. Vic LaBantschnig from Ackerman Buick called me the other night and told me of two Buicks they had recently aquired from an estate. The two Cars are supposed to be like new with less than 50,000 miles on them and all original. They have both been in dry storage since 1964. One is a 1938 Special series 41 and the other one is a 1937 series 41 Sedan. They have cleaned the fuel tanks and both cars run and look very good. I have not seen these cars, but if any of you are interested you can call Vic and get more details on them. He said they were looking for \$10,000.00 for the pair. Since I was un-able to afford them I have not looked or asked what he wanted for each car by its self

CONTACT: ACKERMAN BUICK ST. LOUIS, MO. 314-524-2909

DAVI

PAGE 13





Those who get around a lot were first to take to the new Buick, with the result that a roll call of present Buick ROAD.

MASTER owners reads like a digest of our most socially active families. For getting around is both easy and pleasant in this brilliantly behaved traveler; it is not only inches bigger and blessedly smoother, but agile with the energy of 141 horse-power that can flash you from ten up

even more to ROADMASTER than meets your appreciative eye — so much more that we doubt if you can match its merit within a thousand dollars of its price.



Palms and Burels fine the roads





Buick

Del Sigle #8



MEMBER CARS

1937 Series 41. Francesco Mirabile #354. Brussels, Belgium

PROUD 1937 OWNER



1938 Series 46C. Paul Cusano #52

PROUD 1938 OWNER





A MEMBER SUPPORTED

MEMBER CARS

1937 Series 67. Chris Smith #189 Looks Great with Her New Paint Job

PROUD 1937




1937 Series 41. What a Beauty!!

PAT DAKIN #18

PROUD 1937 OWNER







- BELT WEATHERSTRIP
- RUBBER WEATHERSTRIP
- GLASS SETTING CHANNELS
- FOLL RUBBER MATTING
- RUBBER BUMPERS & GROMMETS
- SEDAN DECKING
- BIAS, WELTS &
- · FENDERWELT
- CLIPS & FASTENERS
- · MOULDING BOLTS
- STAINLESS
- FINISHING WASHERS
- BUMPER BOLTS
- TRIMMING SUNDRIES

WINDBER, PA. 15963


Illustrated Catalog \$2.00



Support Our

BUICK STEERING WHEELS

1937 THRU 1947



P. O. BOX 328 DEPT. B

Beautifully recast to your orig. center. Mold and color from N.O.S. Center Plastic also available.

> Send \$1.50 check for brochure and color print to: (please state year)

> > J.B.Donaldson Co.

701 N. 22nd Ave.

Phoenix, Arizona 85009



MEMBER CARS

1937 Series 44..A Rare Car. Two Door Sedan, Slant Back Special Car is in the process of a Ground up Restoration.

AL KINDBERG #337





Hi Dave.

I just wanted to drop you a few lines to tell you how much I enjoy your book. I wish this book was out while I was restoring my '38 Buick. It would have been very nice, what with all the parts the fellow members seem to have. Don't feel bad when your book is late, because I am sure everybody feels like I do, that the book is worth waiting for I sent three pictures of my car, before and after. I bought my 1938 46S in Newark, Ohio in 1968 and although everything was there, my work was cut out.

The body was never off of the frame, but everything else came apart. I rebuilt the

engine and drive line and did the body and paint work myself.

We took the car to the outing in the spring of 1973 and in 1974 I found welled fenders for it. In 1979 I took the whole car back apart and completely went over everything,

including the front suspension.

The car has radio, heater with defroster, front and rear signal lights and 7-16 tires. I repainted it and re-woodgrained the dash and garnish moldings. It has a new interior with the compliments of my wife's sewing. I hope to have it ready for the '83 Nationals. Although all work is amateur, my wife and I are very proud of our '38. Hope to meet you in person in '83.

0 1956

John Chuppa #196

Support Our ADVERTISERS

ANTIQUE CARS AND PARTS
UPHOLSTERY CARPETING
CONVERTIBLE TOPS



RD 2, Box 137 Annandale, New Jersey 08 201 - 236 - 2403

BOB'S AUTOMOBILIA IS ONE OF THE MAJOR SUPPLIERS OF TOP QUALITY BUICK PARTS......

BELOW IS A SAMPLE OF JUST SOME OF WHAT BOB CARRIES.

1938 BUICK MAP LIGHT COVERS\$35	
1937/38 CENTER HOOD STAINLESS. \$99	
DOOR SILLS, CUT TO LENGTH (45") \$3000	
GRILL & CENTER STRIP EMBLEMS. \$25	
NEW BANJO-STEERING WHEELS. \$225	
VOUR HINGE PIN & BUSHING KIT &O EA .	2
OUISIDE DOOR HANDLE RET. Screws.	
STAINLESS STEEL \$0 5000	,
37 RADIO GLASS, SILK SCREEN \$14	

37 INSTRUMENT PANEL GLASS, SILK SCREEN
DECALS FOR TEMP, GAS OIL SPEED &BATTERY
COMPLETE SET OF DECALS......\$10 set,
INCLUDES CLOCK
CONVERTABLE TOP MOULDING, BRASS OVER LEAD,
a.WITH NAILS INBEDDED......\$8.50 Ft.

STEERING COLUMN TO FLOOR GROMET, BLACK....\$6
SIDEMOUNT NUTS, CAD PLATED......\$4 ea.
FRONT FLOOR MATS.....\$150

AND WE ALSO CARRY THE FOLLOWING.....

RUBBER MOUNTING PADS....HEADLINERS.....CONVERTABLE TOPS....UPHOLSTERY...ENGINE PAINT..

DECALS...LITERATURE...BUICK LOCK ROLL HOSE CLAMPS...WIRING HARNESSES...DASH AND DOOR

PLASTIC KNOBS AND MUCH MUCH MORE...CATALOG \$2.00..SEND FOR YOURS NOW.

BUICK CLUB DISCOUNT OF 20% OFF

PENN BALL BEARING CO. 3511 N. American St. Phila., PA 19140



Telephone: GArfield 3-3105

BEARINGS

WE CARRY IN STOCK-

A B C AETNA ANDREWS A T B AUBURN BANTAM B C A BOWER C J B DODGE FAFNIR FEDERAL

GWILLIAM
HEIM
HOOVER
HYATT
KILIAN
LINK BELT
MCGILL
M R C
MEDART
NEW DEPARTURE
NICE
NORMA HOFFMAN

ORANGE POLLARD R B C ROLLWAY SAGINAW SCHATZ SEALMASTER SHAFER S K F TIMKEN TORRINGTON TYSON

OIL SEALS

C/R, TROSTEL, NATIONAL, VICTOR, GARLOCK, GITS

Support Our ADVERTISERS



NATIONAL BUICK C

RAY KUEHN

DOOR SILLS

81 GRAHAM AVE.

N. HALEDON N. J. 07508



TECHNICAL TIPS

THANKS TO PAUL BRENNAN #71

New	Passenger	Car	Regist	rationst
	- mooning or	-154 V	Transfer of the second	L'ELFT CATEC

Auburn	1929 17,850	1930	1931	1932	1933	1934	1935	1936	1937	1938
Martin	Market	11,270 4,364	29,536	11,846	5.038 3.675	5.536 1.057	5.163	1,818	146	*70
Duick	*172.307	*122.656	90.873	49,708	43,829	63,057	87,635	160,687	205,297	165.38
Chevrolet	780,011	12,078 618,894	11,138 583,429	6.259 322,860	3,903	4,293	5,692	11,756	11,231	10.63
	84,518	60,908	52,650	25,015	474,493 28,677	534,998 28,052	40,536	930,250 58,698	768.040 91,622	464.33
Continental	799		Wales		3,310	953	11.000			40,10
De Seur	59,614	1,879 35,267	1,418 28,430	335	91 900	11.114		1.174	1,149	
De Vaux Dodge Durant Ford Franklin	30,014	23,201	4,808	25,311 1,358	21,260	11,447	26,952	45,088	74,424	35.25
Durant	115.773	64,105	53,090	28,111	85,062	90,139	178,770	248,518	255,258	104,88
Ford	1,310,135	1,055,097	7,229 528,581	1,135	*****	*** ***	*** ***			
	10,704	7,482	3,881	258,927 1,829	1,329	530,528	826,519	748,554	785,933	363.68
	60,487	30,140	19.209	12.858	10,128	12.597	15.955	16,439	13,984	6,12
Hudsen Hupmobile La Favette	62,692 44,337	30,468 24,387	19,189	8,641	2,946	19.307	21.587	20,825	90,013	40,83
La Fayette		27,307	11,462	10.794	6,725	8,556 9,301	7,450 17,445	1,556	403	1.02
La Salle	20,290	11,262	6.883	3,848	3.709	5,182	11,775	13,992	28,939	15,73
marinon.	*22,323	4.356 *12,369	3,466 5,687	3,179	2,112	2,061	2,370	15,567	25,243	16,99
micreury			2,007	1,385	86	W11111	*****		41-1-1	8,83
THE RESERVE OF THE PARTY OF THE	105,146 31,830	51,086	39,366	20,233	11,353	14,315	17.739	*43,070	70,571	31,81
Didsmobile	*93.483	21,848 *50,510	12,985	24,128	35,295	** ***				
	44,634	28,318	16,256	11,058	9,081	6,552	149.375 37.653	178.488 68,772	188.306 95.455	92,35 49,16
Pierce-Arrow Plymouth	8,386	8,795	4,522	2,692	2,152	1,740	875	787	167	1
	84,969 158,272	64,301 68,389	94,289 73,148	111,926 47,926	249,667 85,348	302,557 72,645	382,985	499,580	462,758	286,21
PER CO	17,319	11,450	6,762	3,870	3,623	3,854	140,122 3,894	3,146	212, 403	98,39
Studehakee	89 838	62 692	2	16,968	14.554				100	
Persolana /Fesset	191,331	56,526 83,338	46,533 42,545	25,002 28,778	21,668 35,831	41,560	39,573	67,835	70.048	41,50
	162.366	51,487	42,936	22,463	15,314	6,576	53,838 10,439	78,471 12,423	51,411	13.01
Willys-Knight Miscellaneous	37,343	14,079	H.405	3,415	353					
	31,046	9,632	3,518	3,732	1,159	324	1.858	5.294	1,441	79
Total	3,880,246	2,625,979	1,908,141	1,095,399	1,493.794	1,888,557	2,743,998	3,435,497	3.403.752	1,891.02
			By M:	nufactu	ring Gro	ups				
Chrysler Corp.	344,874	224,581				The state of the s				
and Mater Co.	1,316,286	1,059,453	532,047	191,364 262,106	395,656	432,195 532,589	629,243 828,899	851,884	883.572	472,50
December midliges	1,271,129	905, 427	825,437	454,739	646,556	732,375	1,052,297	764_121 1,466,852	791,178	387,51
All Others	947,917	436,518	322,198	98,190	148,347	171,398	233,479	321,640	394,818	163.05
! Data from R. L. Polk & Co.										
		In	Percen	tage of '	Total by	Makes				
	1929	1930	1931	1932			1025		1944	
Auburn	.46	.43	1.55	1,06	1933	1934	1935	1936	1937	1938
Austin		.17	. 15		.34	.06	_19	,05		*.0
PURCH	4,44	4.67	4.76	4.53	2,93	3,34	3.19	4.72	5.89	8.8
adillar hevrolet	20,10	23.57	30,59	.57	.28	. 28	. 24	. 35	.32	5
	2.18	2.32	2,76	29,46	1.92	28.32	23.93	27.33 1.72	22.05	24.5
Liportimental		.07			.22	.05	7.40	1,12	2.63	2,4
De Soto	1.54	1,34	1.49	.03				.03	.93	
DE ASUX	- constant	1,04	.20	2.31	1.42	.61	.98	1,32	2.14	1,8
	2.98	2.44	2,78	2.56	5.78	4.77	6.52	7,30	7,33	5.5
Durant Ford	33,78	40.18	27.70	.10	22 44	40.00				
Panklin	.28	. 23	.20	23,62	20,63	28,09	39.12	21.99	21.99	19.2
aranam	1.56	1.15	1.01	1,17	.68	.68	.58	.43	.40	. 2
fudson	1.62	1.16	1,01	.79	.20	1.02	.79	.61	2.58	2.1
			191	.93	,45	.35	.27	.05	.01	0
	.52	. 43	,36	.35	.25	.27	.43	.41	. 83	.8
incoln	.16	.17	.18	.29	.14	.11	.09	.46	,72	.9
			.30	.12	10.					.3
THE RESERVE TO A PROPERTY OF THE PARTY OF TH	2.71	1.95	2.06	1.85	.76	.78	.65	1.27	2.03	1.6
Mamobile	2.41	1.92	.68	2.20						
ackard	1.15	1.08	2.46	1.01	2.38	3.80	5,44	5.25	5.41	4.8
	.22	.26	.24	. 25	.14	.09	.03	.02	2.74	2,8
ontiac	4.08	2,45	4,94 3,83	10.21	16.71	16.02	13,90	14.68	13,27	15.1
	.45	.44	.35	4.37	5.71	3.85	5.11	5.04	6.10	5.2
todebalas	******	Acres 1	44	1.55	.97			.49		
erraplane (Essex)	2,13 4,93	2.15	2.44	2,28	1.45	2.20	1.44	1.99	2.01	2.1
Villya-Whippet	4.18	1,97	2.25	2.62	1.03	2,15	1.96	2.30	1.47	
Villys-Knight Aleceilaneous	.98	.54	.44	.31	,02			.35	1.47	.6
	.82	.35	,20	.35	80.	.01	.07	.16	.05	.0
Total	100,00	100.00	100,00	100.00	100.00	100,00	100,00	100.00	100,00	100.0
			By Ma	nufactur	ing Grou	ips				
hrysler Corp.	8.89	8.55	11.97	17.45	25,82	22.89	22,91	25.02	70 30	24.4
ord Motor Co.	33.92	40.34	27.88	23.91	20.97	28,20	30.21	25.02 22.44	25.36 22.71	24.9
	32.75	34.48	43.26	41.48	43,28	39.84	38.35	43.09	40.80	44.8
Il Others	24 44	16.63	10 00	12 10						
Deneral Motors	24.44	16.63	16.89	17.16	9.93	9.07	8.51	9.45	11.33	9.8
Il Others *1929-1930 Buick includes Marquette, Marmon includes Roosevett.	-	16.63 -1931 Oldsmobile Inclu		-	9.93 ash includes La	*1938-		-	11.33 *1937-193 plane included w	18



CONTACT ANY OF US: DAVE LEWIS #237

JAVE LEWIS #237 3825 So. Second St SPRINGFIELD.ILL 62703 DOUG BECKER #96 3032 W.Olive Branch GREENWOOD, IN 46142

JOHN STEED #132 6274 BLUFF ACRES DR GREENWOOD, IN. 46142

Support Our

ADVERTISERS



NATIONAL BUICK CLUB

STEELE

PROUDLY ANNOUNCES

The publication and availability of the 1983 issue of our catalog of Quality Reproduction Rubber Parts for BUICK! Complete the coupon and send it in with \$1.00 today!

LYNN H. STEELE Dept. 37-38 Route 1, Box 71W Denver, NC 28037 (704) 483-9343 こうけん かいかん かいかい かいかい かいかい かんかん かんかん しゅう かんしゅん しゅんしゅん しゅんしゅん しゅんしゅん

Name			
Address _			
City			
State		Zfp	
Yr	Make		Md1


Support Our ADVERTISERS








1937+1938 Steering Wheels. Strong PVC Cream Colored Plastic. 225.00 each





1937-38 Door Sill Plates. Trim to fit, 1 per door. 15.00 each





1938 Rear Tube Type Shock Absorbers. 79.00 pair



1937-38 Radiator Caps. 5.00 each



1937-38 Bumper Bolts. Made entirely of Stainless Steel. 7.00 each



Front Stabilizer Repair Kits. 7.50 pair

المدار لا على المدار لا عدا ومدر والمتسدق المد King Bolt Kits. Complete Repair Kits. 25.00 ea.

Battery Hold Down Bolts. 5.00 per pair



1937-38 Fuel Pump Repair Kits. 16.00 each.



1937-38 Gas Caps. 5.00 ea.



1937-38 Thermostats 4.50 ea.

As part of our service to you, we can also supply the following:

- * LEVER ACTION SHOCK ABSORBER SERVICE
- * A COMPLETE LINE OF BRAKE SERVICE PARTS
- * QUALITY DECALS, STICKERS AND TAGS * COMPLETE IGNITION AND TUNE UP PARTS
- * OIL FILTERS AND GAS FILTERS
- * EXHAUST SYSTEMS AND COMPONENTS
- * WHEEL BEARINGS AND SEALS
- * CLUTCH BEARINGS, PLATES AND DISCS
- * A COMPLETE LINE OF RUBBER PARTS FOR BODY AND SUSPENSION INCLUDING MOUNTING PADS, WEATHERSTRIPPING AND GROMMETS
- * OVERHAUL GASKETS SETS, MANIFOLD SETS * WATER PUMP KITS AND REBUILDING SERVICE
- * AIR DUCT AND DEFROSTER HOSE
- * BATTERY CABLES
- * CLOCK, RADIO AND SPEEDOMETER REPAIR

We are always looking for new sources and supplies to upgrade our inventory and service to our customers. Please send 2.00 for complete catalog containing New, Used and Reproduction parts for 1937 and 1938.





GLENN D. CECCHINE (201) 685-0581 14 MOUNTAIN AVE SOMERVILLE N.J. 08876

Support Our ADVERTISERS

VENT WINDOW WEATHERSTRIP

C-38A	1936 1937	Styles 4467,4667,4829 Style 4829	\$ 53.00
C-38H	1936 1937	Styles 4419, 4619, 4819, 4919, 4923, 4933 Ser. 80 & 90 except convertible	\$ 53.00
C-38E	1937-38	Series 40 & 50 except convertible	\$ 48.00
C-386	1937-38	Series 40 & 60 convertibles	\$ 53.00
C-38C	1938-40	Series 80 & 90 convertibles	\$ 58.00

E S

1933-60 W'strip, vent window div-ision bar, front or rear door & divided quarter window. Rubber only. Cement to orig. metal channel. Approx. 30" strip, enough for 2 vents. C-40 6.50/ea.



C-347

1933-56 Channel, rigid run, win-1933-56 Channel, rigid run, window division bar, stainless beaded edge, mohair-lined, exact replacement for rear side of division bar. Fastens in place by small screws or rivets, top & bottom. Simply cut to exact length req'd. & drill 2 small Approx. 15" long, many models as req'd.

. \$ 20.00/pr.





1933-56 Window run channel. chrome beaded edge, cloth covered, mohair lined flexi-ble metal channel for sides å top of door windows. Per fect dimensions, 5/8" wide x 9/16" overall height.

exact replacement. Mos closed models. Specify which length desired. 6' strip -\$ 14.50/ea.



1937-57 Weatherstrip, door window inner & outer, front & rear doors. 7/16" wide x 36", with chrome bead, mohair faced, flexible. Trim length where necessary. Two 3' strips. Most models. C-555 \$ 16.50/pr.





TO ORDER: list quantity, part number, and price, include 10% for packaging and shipping (NC residents also include 3% state sales tax). Orders accepted on a prepaid, cash C.O.D., or Visa/Mastercard charge basis. 1983 CATALOGS covering Buick or any other American make, except Ford, are available for \$1.00 per car make.

STEELE

Dept. 37-38 Rt. 1, Box 71W Denver, N.C. 28037 (704) 483-9343

"It's Buick again!" MONEY GOES FARTHER IN A GENERAL MOTORS CAR



NATIONAL BUICK CLUI A MEMBER SUPPORTED

18-41 S-P. 4-D 18-41 S-P. 4-D 18-46 S-P. 2-D 18-46 2-P. Bus 18-46C 4-P. Cor 18-46S 4-P. Spo 18-47 S-P. 4-D)	The same of the sa		Dally's Price	With 5 Wheel With 6 Wheel		Dear Third 1	25 Menth II	it should li	It Meath	UPROLATERY OPTIONS
U m	5-P. 4-Dr. Conv. Strmline Spt. Phae.	3705	\$1406					-	-	A CONTROL OF THE PROPERTY OF T
U m	5-P. 4-Dr. Tourg. Sedom (Trunk Bk.)	3560	\$1047		-	4.	-	-	Ī	
U in	5-P. 2-Dr. Streamline Sport Sedan	3515	\$ 981	-	+	1		-		to WALREST SECURIS AND COUNTY NO 400, THE BESTSON ONE OF ALL TANK AND AND THE TANK THE LEADERS WHICH WAS AND
U m	2-P. Business Coupe	3385	\$ 945		-	-				
to	4-P. Conv. Coupe (Rumble Seat)	3575	\$1103	-	1	7		-		48 SERIER-CONVENTIBLE COUPER AND PILATIONS: No 441, Tan Bestund Core Landborn shisleship at 80 estra rest: No 444, Risch: No 445, Ton. No 446, Orey No 441, Octors:
	4-P. Sport Coupe (Opera Seats)	3425	\$1001		-	-	1	-	1	No. 448, Blass: No. 448, Red Combined stells and bashes trim sokalmable at no extra yeat. No. 446, Chatt and Higgs to the there No. 441 Chatt and Ton Locale and the second
	5.P. 4-Dr. Streamline Sport Sedan	3535	\$1022			+	-		3	Leather; Mo. 484. Chelh and Blue Leather. No. 431, Cluff, and Red Leather.
18-48 5-P. 2-D	5-P. 2-Dr. Tourg. Sedan (Trunk Bk.)	3520	\$1006				+	+	T	
38-60C 5-P. 4-D	5-P. 4-Dr. Conv. Strmline Spt. Phae.		\$1713		-	-	-	-	-	
18-61 5-P. 4-D	5-P. 4-Dr. Tourg. Sedam (Trunk Bk.)	3780	\$1297	-	-	-	-	-	Ī	I. No 458, Grey Bedford Card. No 428, Tan Badford
18-66C 4-P. Cor	4-P. Conv. Coupe (Rumble Seat)	3815	\$1359	1		4			-	Learners estatements of retry west: No. 452, Black. No. 486, Tant. No. 464, Cray, No. 408, Cp-en. No. 404, Black. No. 407, Ref.
18-66S 4-P. Spo	4-P. Sport Coupe (Opera Seats)	3690	\$1226			****	* ******			SERRES—CONVENTINE COUPES AND PHALTONE. In: 416, Tan Bestors Deed feathers obtainable at sea sates end; No. 431, Mood No. 441, Tan. No. 420, Over: No. 441, Deserv.
18-67 5-P. 4-D	5-P. 4-Dr. Streamline Sport Sedan	3785	\$1272	-	-	1	-			No 461, Blue: No. 462, Red. Combined cietà and leather frim abialankle at no exira coat: No. 462, Cloth and Bluck Leather:
18-68 S-P. 2-D	5-P. 2-Dr. Tourg, Sedan (Trunk Bk.)	3760	\$1256			-		-	1	No 464, Cloth and Tan Leather: No. 469, Cloth and Grey Leather: No. 469, Cloth and Green-Leather: No. 467, Cloth and Blue Leather: No. 488, Cloth and Blue Leather:
18-80C 6-P. 4-Dr	6-P. 4-Dr. Conv. Strmline Spt. Phas.		\$1983		-	-	-	-		B RERES SEDARS No. 411, Orry Beffred Ord; No. 412, Tan Bedford Gord; No. 413, Grey
18-81 6-P. 4-D	6-P. 4-Dr. Tourg. Sedan (Trunk Bk.)	4245	\$1645			+-	-			rest! No. 418, Nisky: No. 417, Tan. No. 418, Crep: No. 418, Creen: No. 429, March No. 431, Nisky: Nisky: No. 431, Nisky: Nisk
18-81F 6-P. 4-D	6-P. 4-Dr. Formal Sedan (Trunk Bk.)		\$1758				-			No. 471. Tan Brondeloth: Me. 472. Grey Standeloth. Lendare shallands a last series seed. St. 472. St. 472. Tan. 172. 473. Grey No. 473. Grey St. 473. St. 473. Grey No. 473. Grey St. 473. St. 473. St. 473. Grey St. 474. St. 473. St. 473. St. 473. Grey St. 474. St. 473. St. 473. St. 473. St. 473. St. 473. St. 473. St. 474. St.
18-87 6-P. 4-Dr	6-P. 4-Dr. Streamline Sport Sedan		\$1645			-	-		1	Yill Orey Bedford Coed and Black Leather; No. 480. Tan Bedford Cord and Tan Leather. No. 481, Over Bedford Cord and Over Leather; No. 481, Tan Bedford Cold and Over Leather; No. 481, Over Bedford Cord and Blot Leather; No. 481, Tan Bedford Cord and Rod Leather; No. 481,
38-90 8-P. 4-Dr	8-P. 4-Dr. Tourg. Sedon (Trunk Bk.)		\$2350			-	-		T	Der BEREB. GEDAM MODELS: No. Cts. Orey Bedfeid Ones, No. 423. Tan Bestjord Cord; No. 434.
18-90L 8-P. 4-Dr	8-P. 4-Dr. Limousine (Trunk Back)		\$2453			-		-	T	No. 421, Tani No. 423, Grey No. 439, Green W. 453 Gless No. 431, Red. Modella No. 431, R
18-91 6-P. 4-Dr	6-P. 4-Dr. Tourg. Sedan (Trunk Bk.)		\$2176				-		T	Abberts efetablishe at estre see—Mear semperteest; N. C.M. Brist, CT. Yan. Opt. Over. 25. Oven: 444. Shirt: 451, 264. Fresi esmparteest; No. 451, Tan. Not. 454-438-438-454-46, all Sinck. Completions at he active sea.

CONVENTIBLE MODEL TOP MATERIAL (Oblehable at no extra cost) Series 40.40.80 cryp 11-7, Black

Technical Research:

Paul Brensan #71 2343 Werner Manguette, 906-226-861,





TECHNICAL TIPS

A history of the sidemount spare

In 1937 through 1940 all series 80 and 90 cars were shown with six wheels, and many of the other models were also shown that way. The 1937 Salesman's Fact Book made the point that now buyers did not have to take sidemounts on convertible coupes since a tire compartment beneath the rumble seat was provided (as on other GM cars). The Roadmaster convertible sedans were, it was stated, available only with six wheels. There is no evidence to suggest that single mounts were offered at any time, as happened on Cadillac.

In both the 1938 and 1939 catalogs the majority of cars were shown with sidemounts but in neither was any mention made as to optional or standard equipment. Two illustrations of open tranks in the 1939 edition failed to mention added capacity when the spare was sidemounted. In 1939, for the first time (and again in 1940) two styles of sidemounts were offered; the one on the big cars was essentially similar although not identical to the previous year, and the mount on the Special and Century was entirely different. This latter mounting was at hest very awkward and clung to the side of the car rather than fitting into a well. Covers were different, too; senior Buick covers closely resembled 1938 covers, but covers on the small

Buicks, while slightly contoured had chrome trim. Apparently buyers resisted this clumsy design and Buick redesigned the front fenders for the 1940 small cars. Front doors simply could not be opened as far on 6-wheel small Buicks as on those same models without sidemounts. In order to prevent doors from hitting the sidemounts, front door eheck links were shorter on 6-wheel cars. The 1940 catalog of the small Buicks showed several cars with sidemounts and included a sketch under the illustration of the Century convertible sedan that showed a covered wheel mounted in a fender. The caption stated, "The smart lines of this spacious convertible are enhanced by the use of sidemounts, available at added cost." This is perhaps one of the most direct promotions of sidemounted wheel equipment by any maker in the last years of its availability. The 1940 Buick Deluxe Limited brochure showed all cars with sidemounts but does not mention that they were optional at extra cost. By 1941 slab-sided styling precluded sidemounts even on the senior cars.

Costs remained fairly constant in the last 4 years of the 6-wheel option. In 1937 6-wheel equipment included bumpers and guards, two tires and tubes, dual windshield wipers, two metal covers, two tire locks, two fen-

derwells, spring covers, dual taillights, dual signal horns, two extra wheels and two side tire carriers, all for a cost of \$95 on the Special, \$100 on the Century, \$105 on the Roadmaster and \$140 on the Limited. The same extras and 5-wheel equipment cost \$40 less, resulting in an actual price for sidemounts of \$55, \$60, \$65 and \$100. In 1938 and 1939 six wheels were standard on the Limited (they could be removed optionally if desired) and cost \$45 on Specials and Centurys and \$60 on the Roadmaster. The prices in 1940 were \$47 on small cars and \$62 on senior cars. Tire covers from 1931 through 1935 were two-piece metal units that exposed the wheel. In 1936 through 1939 full contour covers were used. For 1940 smooth-sided covers were seen, and used restrained trim on the senior cars but a bit more on the small series. Wheels were higher on the small cars than on the senior models and fenders also reflected the difference in size. An educated guess on production (figures are not available) suggests that about 75-95% of senior Buicks were equipped with sidemounts. Small Buicks with six wheels varied in number between 20-30% in 1936; in 1937-38, the big years for sidemounts, 30-35% probably had sidemounts: 10-20% of the 1939-40 cars may have had this option.



1938 Buick Roadmaster convertible phaeton



A MEMBER SUPPORTED

NATIONAL BUICK CLUB

TECHNICAL TIP

A completely automatic device

MAY 1938

HILL HOLDER

This device, called "NoRoL" by its manufacturer, provides greater ease of vehicular control on hills and in traffic. It is connected to the clutch pedal, Fig. 65, and keeps the brakes applied as long as the clutch pedal is depressed when the car is on an upgrade, even after the brake pedal is released. The driver is then able to use his right foot for the accelerator pedal.

The hill holder is connected hydraulically between the brake master cylinder and the wheel cylinders. Brake fluid from the master cylinder enters the inlet of the hill holder and passes through the outlet to the wheel cylinders when the brake pedal is depressed. Within the hill holder is a valve operated by a ball cage and a steel ball within the cage. The position of the ball cage is con-trolled by a camshaft operated by linkage from the clutch pedal.

Fig. 66 illustrates the position of the ball cage when the clutch pedal is re-leased. When the clutch pedal is de-pressed, Fig. 67, the operating lever is pulled to the left and turns the cam-shaft so that the ball cage fits into the flat surface on the camshaft. The spring then forces the ball cage to the right so that the rubber seal is pressed against the valve seat.

When the car is stopped on an upgrade with the brakes applied and the clutch pedal depressed, the ball rolls against the rubber seal which, in turn, rests against the valve seat, preventing the brake fluid in the wheel cylinders from returning to the master cylinder. Pressure is therefore maintained in the wheel cylinders to keep the brakes applied.

When the clutch pedal is released, the camshaft is rotated and lifts the ball cage away from the valve seat, allowing brake fluid to pass through the valve to the master cylinder, thus releasing

the brakes.

When the car is on a downgrade, the ball rolls away from the rubber seal, rendering the valve inoperative regardless of clutch pedal position.

The hill holder does not affect the ordinary use of the brakes for when the brakes are applied pressure of the fluid

brakes are applied, pressure of the fluid from the master cylinder forces the ball cage back against the spring even if the clutch pedal is depressed, allowing fluid to flow through the outlet through the wheel cylinders.

HILL HOLDER ADJUSTMENT-In adjusting the hill holder, first be sure it is This can be determined with a spirit level mounted on the two bosses on top of the housing.

The control rod, which is connected to the lever, must be so set that the brakes release just ahead of clutch engagement or when the car begins to accelerate. If brake release is delayed, the effective rod length should be shortened. Should the brakes release too quickly-permitting the car to move backward before clutch engages-the rod should be lengthened.



Nothing new to learn. Keeps your hands on wheel and your right foot free for accelerator duty. Halts unnecessary clutch wear

From now on, stopping and starting on hills and inclines can be as simple, and safe, as this:

- 1. Disengage clutch and apply brakes.
- 2. Remove your foot from the brake. Place it in readiness on the accelerator pedal and shift gears.
- 3. Engage the clutch; accelerate the motor and move forward.

No more grabbing at the hand brake. No more jumping from brake to accelerator. No more riding the clutch. No back roll and jerky starts!

Buick's new NO-ROL brings this new safety and comfort to you. Quickly attached to the brake master cylinder, this thoroughly proved, completely automatic device retains brake pressure after the brake pedal is released—as long as the clutch is disengaged. Brake pressure is released when the clutch is re-engaged.



The completely automatic Buick NO-ROL attaches quickly to the brake moster cylinder

The Buick NO-ROL, for all 1938 model Buicks


ONLY \$800 Plus small inetallation charge


NO-ROL does not operate when the car is moving or when stopped on a downgrade. It operates only when the car stops on an upgrade, because its action is controlled by gravity acting on a steel ball.

See this new safety and convenience device today at the address given on the back cover of this magazine. Your Buick dealer will be glad to demonstrate its efficient action.



TECHNICAL TIPS








Fig. 67 Sectional view of hill holder when clutch pedal is depressed

NO-ROL DEVICE. 1938 SERIES Buick No-Rol Device is available for all 1938 series.

Shipments are made direct from Factory stocks at Flint as follows:

1938	Group No.	Part No.	List	Dealer Net
40 Series 60-80-90 Series	4.642	980592 980593	\$8.00	\$4.80 4.80

Each Buick No-Rol is packaged complete with instructions and special fittings for the series specified.

No-Rol attaches to the brake master cylinder and its action is that on an up grade or hill when the car is brought to a stop by disengaging the clutch and applying the foot brake, a gravity-operated valve retains the oil pressure in the braking system thereby preventing the car from rolling backward. For this reason, the foot may be removed from the brake pedal and used to operate the accelerator without applying the parking brake.

As long as the clutch is disengaged, No-Rol keeps the brakes applied. When the clutch is released in starting the car, No-Rol automatically releases the brakes.

Among the desirable features of this device are its ease of installation and freedom from critical adjustments.

Buick No-Rol is not available for past model Buick cars.

Technical Kesearc

Paul Brennan #71 2#43 Werner Marquette, M. 49 906-226-8617 Technical Directo



TECHNICAL TIPS




Figure No. 208 1927 BUICK 40 AND 60 CONVERTIBLE COUPES Applies to Style Nos. 4467-4667

D-Tail lamp wire-natural with black tracer

E-Stop lamp wire-natural

G-Gas gauge wire-natural with black cross tracer




Figure No. 203 1937 BUICK 40 AND 60 SEDANS AND COACHES

Applies to: 4401-4409-4601-4609 Style Nos.\ 4411-4419-4611-4619

A-Dome lamp to switch wire-natural

B-Dome lamp to switch feed wire-natural with red tracer

C-Dome lamp ground wire-natural with green tracer

1)-Tail lamp wire-natural with black tracer

E-Stop lamp wire-natural

F-License plate lamp wire-white with black parallel tracer

G-Gas gauge wire-natural with black cross tracer

Technical Research:

Payl Brennan #71 2#3 Werner Marquette, M. 49855 906–226–8617 Technical Director



TECHNICAL TIPS




Figure No. 206 1937 BUICE 40 AND 60 BUSINESS AND SPORT COUPES Applies to Style Nos. 4427-4627-4427B

- A-Dome lamp to switch wire-natural
- B-Dome lamp to switch feed wire-natural with red tracer
- C-Dome lamp ground wire-natural with green tracer
- D-Tail lamp wire-natural with black tracer
- E-Stop lamp wire-natural
- G-Gas gauge wire-natural with black cross tracer




Figure No. 213 METHOD OF IDENTIFYING BODY WIRING

Tecrnical Research:

Kuul Brennan 471 2343 Werner Marquette, M. 49855 906–226–8617 Technical Director





NEW MEMBERS

Francesco Mirabile #354 Avenue g Abeloos,19 Box9 1200 Brussels, Belgium 1937-41

Michael J. Kamen #355 312 W. 5th St #900 Los Angeles, CA 90013 37-80 (10) 213-680-1230

Mark Davis #356 108 Haven Ave Staten Island, N.Y. 10306 37-41 (7) 212-351-1787

Patrick Sharkey #357 12 DeFiance St. Ticonderoga, N.Y. 12883 38-40 38-80 585-6016

Robert Hord #358 P.O. Box 291 Orland Park, Ill 60462 37 312-349-0256

Joe Arbini #359 111 Ward Lane Stamford, Conn. 06907 37-40 (9) 38-40 (9.5) 203-324-6653

Pat O'Brien #360 901 Teawood La Habra, CA 90631

James D. Stark #361 N92W37502 O'Neil Rd. Oconomowoc, WI 53066 37-66C (7) 414-474-4113

Jerry Miller #362 144 Ken Rose Ln. Cave Jct,.OR 97523 38-40 [8] 503-592-2482 John Meyers #363 6706 Bennett Corners Rd. Memphis, N.Y. 13112 38-40 (10) 315-689-7817

Bernard B. Covney #364 4470 Darden Ave. Titusville, FLA 32780 37-47 (4) 305-267-3553

Ron Knox #365 6205 Trafalgar Rd RR1 Hornby,ONT.,Canada LOP 10E

Mike Nolte #366 975 Bennett Dr. Elyria, OH 44035 38-90L (5) 216-365-6649

Edward Hallahan #367 108 Paris Ave. Northvale, N.J. 07647

Robert C. Berdan #368 1920 North West 143rd Apt. #44 Portland, OR 97229 37-40 (8) 503-645-0917

John Plough #369 48 Salvador Way San Rafael, CA 94903 37-41S (10) 38 46C (8) 415-472-3163

Marshall Nelson #370 1559 Commercial S.E. Salem, OR 97302 37-80C (8)

Robert L. James #371 P.O. Box 531 Whitby, Ontario, Canada LIN 5V3 37-80C Laverene Russell #372 870 Bluebird Lane Memphis, TN 38116 37-46S (8) 901-332-6129

David Garrison #373 23321 Via Ronda Mission Viejo, CA 92691 37-80 (8) 714-770-6122 (H) 714-640-1770 (O)

Anthony Bertolo #374 115 Overlook Ave. East Hanover, N.J. 07936 38-40 (7) 201-887-2078

J. Bruce Campbell #375 185 Camino Pablo Orinda, CA 94563 37-40 (10) 415-254-6341

Robert E. Carrubba #376 RD 2, Box 137 Annandale, N.J. 08801 Parts Vendor Bob's Automobilia 201-236-2403

Martin Zimmerman #377 R.D. #2, Box 180 East Earl, PA 17519 37-41 [8] 215-445-6860

Donald L. Lobner #378 RR 1, Box 124A Olathe, KS 66061



АDDRESS СОВРЕСТІОМ ВЕQUESTED

3825 S. SECOND ST., SPRINGFIELD, ILLINOIS 62703

MAAP N'SELL NEWS BULLETIN









